



Site Name	Central Asset ID	6 D's	Reasons	Existing species	Planting notes	Replant species
MORTIMER ROAD	4036750	TR: Felling-	Failed/decayed at base, extensive cavity	Sorbus aria sp	To be relocated as a new tree on the planting request list, species and exact position to be confirmed with customer	Malus 'Rudolph'
MORTIMER ROAD	4036746	TR: Felling-	Significant cavities in stem and scaffold	Crataegus monogyna	To be relocated as a new tree on the planting request list, species and exact position to be confirmed with customer	Malus 'Rudolph'
MORTIMER ROAD	4035528	TR: Felling-	Tree failed/root plate lifted	Quercus robur	To be relocated as a new tree on the planting request list, species and exact position to be confirmed with customer	Malus 'Rudolph'
MORTIMER ROAD	4036028	TR: Felling-	Plate lifting, tree failing	Fagus sylvatica	To be relocated as a new tree on the planting request list, species and exact position to be confirmed with customer	Malus 'Rudolph'
MORTIMER ROAD	4036338	TR: Felling-	Dead	Fagus sylvatica	To be relocated as a new tree on the planting request list, species and exact position to be confirmed with customer	Malus 'Rudolph'
MORTIMER ROAD	4036534	TR: Felling-	Dead	Quercus robur	To be relocated as a new tree on the planting request list, species and exact position to be confirmed with customer	Malus 'Rudolph'

MORTIMER ROAD	4035552	TR: Felling-	Included union at 0.3m, low vitality, crown dieback, poor specimen	Fagus sylvatica	To be relocated as a new tree on the planting request list, species and exact position to be confirmed with customer	Malus 'Rudolph'
MORTIMER ROAD	4036084	TR: Felling-	Poor physiological condition, low vitality	Quercus robur	To be relocated as a new tree on the planting request list, species and exact position to be confirmed with customer	Malus 'Rudolph'
MORTIMER ROAD	4035991	TR: Felling-	Root plate failed, tree fallen	Fagus sylvatica	To be relocated as a new tree on the planting request list, species and exact position to be confirmed with customer	Malus 'Rudolph'
MORTIMER ROAD	4036280	TR: Felling-	Extensive bark wounding, ring barked	Sorbus aucuparia	To be relocated as a new tree on the planting request list, species and exact position to be confirmed with customer	Malus 'Rudolph'
MORTIMER ROAD	4036502	TR: Felling-	Substantial bark wounding and historic limb failure	Sorbus aucuparia	To be relocated as a new tree on the planting request list, species and exact position to be confirmed with customer	Malus 'Rudolph'
MORTIMER ROAD	4036705	TR: Felling-	Scaffold limb failure and significant stem cavity	Sorbus aucuparia	To be relocated as a new tree on the planting request list, species and exact position to be confirmed with customer	Malus 'Rudolph'